



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

July 7, 2009

Reviewed: 

Mine Name: B&C Limestone Quarry	Permit Number: M/039/0013
Operator Name: Bryce Haas	Inspection Date: August 26, 2009
Inspector(s): Lynn Kunzler	Time: 1:30 pm
Other Participants: none	Mine Status: Undergoing Reclamation

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Check status of reclamation work.

Inspection Summary:

SITLA had inspected this site and was concerned that there had been no work since our joint June 1, 2009 inspection. After inspecting the site, it was determined that there had been some regrading work on the northwest portion of the quarry area. There had been some work in dis-assembly of the saws in the shop area. Photos were taken from the water tank area so that a known point could be used to compare photos from future inspections.

Conclusions and Recommendations:

There has been limited work since the June inspection. Operator needs to step up efforts to meet the October 31 2009 date to have work completed as verbally agreed to.

Continue to monitor this site when in the area.

Inspector's Signature

Cc: John Blake, SITLA

Bryce Haas, Operator

O:\M039-Sanpete\M0390013-BandCLimestone\inspections\insp-08262009.doc